

Technical References

T12−3AS




T12−4A




Technical References

T16−2A



T16−3A



Thread and all diameters concentricity should be less than 0.05